















Photograph 1
Looking east at basin area.
Pipe leading from plant directly into basin (at east end). Basin labeled as hot water.

Date: 7/12/94

Time: 917

Photograph 2 Looking north at ditch along west end of site. Collects street and parking drainage and plant waste.

Date: 7/12/94

Time: 920

Photograph 3 Looking southwest at condensate discharge to ditch (west end of site). Wetlands along ditch.

Date: 7/12/94

Time: 920

030\003528C.\tss\morion.ft\August 22, 1994

Photograph 4 Looking southwest at hydrogen sulfate stripper, injection well, and well house.

Date: 7/12/94

Time: 925

Photograph 5 Looking west at Morton Salt substation.

Date: 7/12/94

Time: 925

Photograph 6 Looking east at pooled water west of power house.

Date: 7/12/94

Time: 925

Photograph 7 Looking northwest at NPDES outfall 001 into ditch.

Date: 7/12/94

Time: 930

Photograph 8 Looking northeast at Lagoon 1.

Date: 7/12/94

Time: 940



Photograph 9 Looking southwest at the landfill. Note cinder landfill cover.

Date: 7/12/94

Time: 950

Photograph 11 Frame 2 of panoramic view of Lagoon 3 from east to west.

Date: 7/12/94

Time: 950

Photograph 13 Frame 4 of panoramic view of Lagoon 3 looking east to west.

Date: 7/12/93

Time: 950

Photograph 165
Looking north at ditch on the south side of Lagoon 3.

Date: 7/12/94

Time: 955

Photograph 10 Frame 1 of panoramic view of Lagoon 3 from east to west.

Date: 7/12/94

Time: 950

Photograph 12 Frame 3 of panoramic view of Lagoon 3 looking east to west.

030\003528C.\TSS\InORTON.PT\August 24, 1994

Date: 7/12/94

Time: 950

Photograph 14 Looking northeast at white chunks of rock and white liquid at north-end of Lagoon 3.

Date: 7/12/94

Time: 950

Photograph 4 Looking down at outfall to Chippewa Creek.

Date: 7/12/94

Time: 1035







Photograph 18 17
Looking west at wetland vegetation west of access road on the west side of the site.

Date: 7/12/94

Time: 1050

Photograph 19 18 Looking inside at the evaporations in the Morton Salt Manufacturing Plant.

Date: 7/12/94 Time: 1110

Photograph 20 19 Looking inside at the Morton Salt container manufacturing equipment.









Entrances to Quarry looking North, note apartments on right Entrance and Quarry area looking NW.


anarry entrance looking NW.

note standing water in canter of
picture. Tree line in background
is the edge of the river bank

picture shower berm on side road looking E.

















Photograph No. 1 Orientation: West

Area of exposed waste showing rusted drums Description:

Location: Exposed waste area Date: July 28, 1994



Photograph No. 2 Orientation: North

Description: Exposed waste area showing bulk waste material Location: Exposed waste area Date: July 28, 1994



Photograph No. 3 Location: Exposed waste area

Orientation: South Date: July 28, 1994

Description: Exposed waste area showing rusted drum with solid waste inside



Photograph No. 4 Orientation: East

Description: Tanks full of water and leaves in exposed waste area

Location: Exposed waste area Date: July 28, 1994




Photograph No. 5
Orientation: North
Description: Photograph of landfill area showing well established vegetation Location: South of site Date: July 28, 1994



Photograph No. 6
Orientation: Northwest
Description: Drainage pipe near the Scioto River

Location: Bank of Scioto River Date: July 28, 1994



Photograph No. 7
Orientation: North
Location: Bank of Scioto River
Date: July 28, 1994

Description: Water discharged to the Scioto River via drain pipe



Photograph No. 8 Location: Maintenance building Orientation: West Date: July 28, 1994

Description: Gas monitoring well GSW-1 near maintenance building



1-29-74
10:30 a.m.
marble Cliff Quaries
darge pit area north of
Trabue west of sciots
Sooking N.W.



1-29-74
10:00 a.m.
marble Cliff Quarries
Lauge pit south of Trabus,
east of mcKinley

Looking west



1-29-74
10:30 a.m.
marble Cliff Quarries
Large fill area moth
of Trabue, west of
Scieto



18-29-74
10:00 a.m.
marble Cliff Quaries
Large Pet immediately
south of Trabue, east of
mcKinley.

Looking north